### ORIGINAL

**COMMISSIONERS** 

**BOB STUMP** 

**BOM BURNS** 

TOM FORESE **DOUG LITTLE** 

PER DECISION 74568.

SUSAN BITTER SMITH, Chairman



5 6 7

8

10

11 12

13 14

> 15 16 17

18 19 20

25 26

29 30

31 32

33 34

35

36

37 38 39

27 28

Brian K. Bozzo

Compliance and Enforcement Manager **Utilities Division** 

on May 14, 2015 to:

1200 West Washington Street Phoenix, AZ 85007

BEFORE THE ARIZONA CORPORATION

RECEIVED

2815 MAY 14 P 2 03

AZ CORP COMMISTA DOCKET CONTROL

IN THE MATTER OF THE APPLICATION OF CHAPARRAL CITY WATER COMPANY FOR A DETERMINATION OF THE CURRENT FAIR VALUE OF ITS UTILITY PLANT AND PROPERTY AND FOR INCREASE IN ITS RATES AND CHARGES BASED THEREON – A SYSTEM IMPROVEMENT BENEFITS SURCHARGE PLAN OF ADMINISTRATION

DOCKET NO. W-02113A-13-0118

**DECISION NO. 74860 & 74568** 

NOTICE OF COMPLIANCE FILING

In compliance with Decision Nos. 74860 and 74568, Chaparral City Water Company

hereby files the attached semi-annual status report as outlined in the System Improvement

Benefit Mechanism (SIB) Plan of Administration as a compliance item in this docket.

RESPECTFULLY SUBMITTED on May 14, 2015.

Sandy Mussey
Sandra L. Murrey

Rate Analyst EPCOR Water Arizona, Inc. 2355 W. Pinnacle Peak Rd, Suite 300 Phoenix, AZ 85027

Original and 13 copies filed on May 14, 2015, with:

Docket Control Arizona Corporation Commission 1200 West Washington Street Phoenix, Arizona 85007

Copies of the foregoing emailed

Arizona Corporation Commission DOCKETED

MAY 1 4 2015

**DOCKETED BY** 



Chaparral City Water Company Docket No. W-02113A-13-0118 Plan of Administration System Improvement Benefit Mechanism ("SIB")

- o SIB Plant Table II (Sample attached as Exhibit 2) The schedule of completed and verified SIB eligible projects from SIB Plant Table I and associated retirements.
- o Total Revenue Requirement The revenue requirement approved in Decision No.
  \_\_\_\_\_\_, plus the SIB Revenue Requirement.
- O SIB Revenue Requirement The revenue requirement equal to the return on investment, income taxes and depreciation expense necessary to support the SIB Plant Table II amounts.
- o SIB Revenue Requirement Efficiency Credit An amount equal to 5 percent of the SIB Revenue Requirement.
- SIB Authorized Revenue Amount equal to the SIB Revenue Requirement less the SIB Revenue Requirement Efficiency Credit plus any SIB True up Adjustment.
- o Gross SIB Surcharge Amount to be shown on customers' bills based on meter sizes without consideration to the SIB Surcharge Efficiency Credit.
- o SIB Surcharge Efficiency Credit An amount equal to 5 percent of the Gross SIB Surcharge to be shown on customers' bills.
- SIB Surcharge The amount equal to the Gross SIB Surcharge less the SIB Surcharge Efficiency Credit to be charged based on meter size, calculated to recover the SIB Authorized Revenue, to be shown on the customers' bills.
- SIB True-up Adjustment An amount to adjust for over or under collection of the SIB Authorized Revenues as compared with the total SIB Surcharges collected for the preceding 12 month period. Each true-up shall also analyze the cumulative over or under collections to include a comparison of all past SIB Authorized Revenues, total SIB Surcharge collections, and prior true-ups to be used in calculation of the SIB true-up surcharge or credit.

### III. SIB RELATED FILINGS

- A. Progress Reports Once a SIB is approved in a decision, the Company must file with Docket Control semi-annual status reports delineating the status of all SIB Eligible Plant, on a project by project basis as listed in SIB Plant Table I, starting 6 months after the decision and every 6 months thereafter.
- B. Reconciliation and True Up Once a SIB Surcharge is implemented, the Company must file annually to true up its SIB Surcharge collections over the

Plan of Administration System Improvement Benefit Mechanism ("SIB")


the most recently updated SIB Plant Table I available unless reference is made to a particular Commission decision.

- o SIB Plant Table II The schedule of completed and verified SIB eligible projects from the latest Commission approved SIB Plant Table I and associated retirements.
- o Total Revenue Requirement The revenue requirement approved in Decision No. 74568, plus the SIB Revenue Requirement.
- O SIB Revenue Requirement The revenue requirement equal to the return on investment, income taxes and depreciation expense necessary to support the SIB Plant Table II amounts.
- o SIB Revenue Requirement Efficiency Credit An amount equal to 5 percent of the SIB Revenue Requirement.
- O SIB Authorized Revenue Amount equal to the SIB Revenue Requirement less the SIB Revenue Requirement Efficiency Credit plus any SIB True up Adjustment.
- Gross SIB Surcharge Amount to be shown on customers' bills based on meter sizes without consideration to the SIB Surcharge Efficiency Credit.
- o SIB Surcharge Efficiency Credit An amount equal to 5 percent of the Gross SIB Surcharge to be shown on customers' bills.
- O SIB Surcharge The amount equal to the Gross SIB Surcharge less the SIB Surcharge Efficiency Credit to be charged, based on meter size, calculated to recover the SIB Authorized Revenue. The SIB Surcharge is to be shown as a separate line item on customers' bills.
- SIB True-up Adjustment An amount to adjust for over- or under-collection of the SIB Authorized Revenues as compared with the total SIB Surcharges collected for the preceding 12 month period. Each SIB true-up shall also analyze the cumulative over- or under-collections to include a comparison of all past SIB Authorized Revenues, total SIB Surcharge collections, and prior true-ups to be used in calculation of the SIB true-up surcharge or credit by meter size.

### SIB RELATED FILINGS

A. Progress Reports – Once a SIB is approved in a decision, the Company must file with Docket Control semi-annual status reports delineating the status of all SIB Eligible Plant, on a project by project basis as listed in the latest Commission

Plan of Administration System Improvement Benefit Mechanism ("SIB")



- B. Reconciliation and True Up Once a SIB Surcharge is implemented, the Company must file annually to true up its SIB Surcharge collections over the preceding twelve months with the SIB Authorized Revenue for that period and establish a surcharge or credit to true up over or under collections, regardless of whether it seeks a new surcharge. The filing dates for these annual true-ups shall be as established in the Commission's Decision approving the SIB Surcharge.
- C. SIB Surcharge Requests To obtain its SIB Surcharge the Company must file the following:
  - 1. SIB Plant Table II<sup>5</sup> (with supporting information and documentation), showing the SIB eligible projects completed for which the Company seeks cost recovery. Such projects must:
    - a. be projects listed in the SIB Plant Table I;
    - b. have been completed by the Company;
    - c. have been verified; and
    - d. be actually serving customers.
  - 2. A summary of Commission approved SIB-eligible projects contemplated for the next twelve (12)-month SIB surcharge period from SIB Plant Table I<sup>6</sup> from Decision No. 74568 to allow the Commission to establish the latest SIB Plant Table I.
  - 3. SIB Schedule A (sample attached as Exhibit 3), showing a calculation of the SIB Revenue Requirement and SIB Revenue Requirement Efficiency Credit, SIB Authorized Revenue, Gross SIB Surcharge, SIB Surcharge Efficiency Credit, and the SIB Surcharge. Schedule A shall be supported by revenue requirements schedules supporting the revenue requirements in

<sup>&</sup>lt;sup>5</sup> Sample attached as Exhibit 2

<sup>&</sup>lt;sup>6</sup> Beginning with its SIB Surcharge Request filing for the second 12-month surcharge period, the Company may request a change from the estimated Cost/Unit (approved in the Company's most recent rate case Decision) due to inflation using the latest calendar year Consumer Price Index (see sample attached as Exhibit 1). This may be done only if the original SIB Plant Table I unit cost did not account for inflation.

### Chaparral City Water Company, PWSID No. 07-017 System Improvement Benefits SIB Progress Report Revised March 9, 2015

The purpose of this report is to update Commission Staff on the progress of the System Improvement Benefits (SIB) projects for the Chaparral City Water System (CCWC). The SIB was approved on June 20, 2014 as part of Decision 74568 for CCWC. This status update includes the projects completed between June 21 and December 31, 2014 as part of the first 12 months of SIB, referred to as SIB Year 1, which dates from June 21, 2014 through June 20, 2015.

### 1. Services

The SIB service line replacement projects for SIB Year 1 are labeled S-1 through S-6 and include replacement of 247 services at a total cost of \$958,558. As of December 31, 2014, 164 services have been replaced. Many of the services planned for replacement during this period did not require replacement; however, the Town of Fountain Hills requested that the service line replacements on El Pueblo Boulevard be completed during SIB Year 1 to coordinate with their paving schedule. These replacements are labeled as project S-22 and will be completed during SIB Year 1. The attached SIB Plant Table I, 1-1 shows the service replacements that were completed as part of projects S-1 though S-6 and includes the service replacements remaining as project S-22. Additionally, the attached maps for projects S-1 through S-6 show the location of the replaced services.

### 2. Valves

The SIB valve replacement projects for SIB Year 1 are labeled V-1 through V-7 and include replacement of 95 valves at a total cost of \$453,491. As of December 31, 2014, 17 valves have been replaced. The Town of Fountain Hills requested that the valve replacements on El Pueblo Boulevard be completed during SIB Year 1 to coordinate with their paving schedule. These replacements are labeled as project V-31 and will be completed during SIB Year 1. The attached SIB Plant Table I, 2-1 shows how many valve replacements were completed as part of projects V-1 through V-7 and includes project V-31. Additionally, the attached maps for projects V-1 and V-4 through V-6 show the location of the replaced valves.

### 3. Hydrants

The SIB hydrant replacement projects for SIB Year 1 are labeled H-1 through H-7 and include replacement of 41 hydrants at a total cost of \$453,491. As of December 31, 2014, none of these hydrants have been replaced. The attached SIB Plant Table I, 3-1 shows the planned hydrant replacements for the remainder of SIB Year 1.

### 4. Meters

The SiB meter replacement project for SiB Year 1 is labeled project M-1 and includes the replacement of 1,507 meters at a total cost of \$314,989. As of December 31, 2014, 592 meters have been replaced. The attached SiB Plant Table I, 4-1 shows how many meters were completed in each meter route as part of project M-1.

### **Attachments**

SIB Plant Table I, 1-1

Project S-01 Map

Project S-02 Map

Project S-03 Map

Project S-04 Map

Project S-05 Map

Project S-06 Map

SIB Plant Table I, 2-1

Project V-01 Map

Project V-04 Map

Project V-05 Map

Project V-06 Map

SIB Plant Table I, 3-1

SIB Plant Table I, 4-1

## Chaparral City Water Company, PWSID No. 07-017 SIB PLANT TABLE I, 1-1 2014 Service Line Replacements

Information to be included with SIB-Eligible Project Filings


| Provide narrative why Replacement Plant is necessary     replacement of existing plant that has exceeded its designated useful life and has worn out or is in deteriorating condition due to no fault of the utility     replacement of existing plant to address excessive water | loss (10% or more) - replacement of existing plant for other reasons supported by persuasive showing by utility | 2. Provide narrative explaining why this segment of plant is a priority. | 3. Provide narrative explaining how replacing this plant will benefit existing customers. | 4. Provide affirmation that Replacement Plant does not include the costs for extending or expanding facilities to serve new customers. | 5. Provide reference to related page No. in the submitted detailed Engineering Analysis supporting the need for SIB. Engineering Analysis shall also include narrative explaining the utility's systematic assessment, inspection, maintenance and repair/replacement program. | Replace 40 residential services (3/4" or 1") on Ocotillo between Mustang and Fountain Hills Blvd. The services are branched black poly lines (one service for two customers) that are failing at a high rate. These services are a priority because they were installed about 40 years ago, in 1974. Replacing the services will help reduce system water loss and improve customer pressure and flow with a single service for each customer. The service line replacements are for existing customers and not related to new growth. See Map No. S-1 in Exhibit CC-1 for the locations of the replacements. | Replace 105 residential services (3/4" or 1") on Mustang between Palisades and Fountain Hills Blvd. The services are branched black poly lines (one service for two customers) that are failing at a high rate. These services are a priority because they were installed about 38 years ago, in 1976. Replacing the services will help reduce system water loss and improve customer pressure and flow with a single service for each customer. The service line replacements are for existing customers and not related to new growth. See Map No. S-2 in Exhibit CC-1 for the locations of the replacements. |
|---|---|--|---|--|--|---|---|
|   | Project<br>Status   |  |   |  |  | 22/40<br>completed,<br>see S-01<br>project map  | 73/105<br>completed,<br>see S-02<br>project map   |
|   | Expected<br>In-Service<br>Date  |  |   |  |  | 6/2015  | 6/2015  |
|   | Site<br>(location<br>description)   |  |   |  |  | Ocotillo  | Mustang   |
| w plant)  | Subtotal<br>Cost<br>(estimated)   |  |   |  |  | \$155,232   | \$407,484   |
| Replacement Plant Description (new plant)<br>(SIB-eligible plant)   | Cost/Unit (estimated) <sup>2</sup>  |  |   |  |  | n/a   | וי/מ  |
| nt Plant De<br>(SIB-eligib  | Cost/Unit (estimated) <sup>1</sup>  |  |   |  |  | \$3,881   | \$3,881   |
| placeme   | Material  |  |   |  |  | Copper  | Copper  |
| Re  | Diameter/<br>Size   |  |   |  |  | 34" & 1"  | %" & I"   |
|   | Units<br>(Quantity)   |  |   |  |  | 40  | 105   |
|   | NARUC<br>Acct No./<br>Plant   | 333<br>Services  |   |  |  | 333   | 333   |
|   | Project<br>No.  |  |   |  |  | 8-1   | S-2   |

<sup>&</sup>lt;sup>1</sup> Per the Commission approved Initial SIB Table I.
<sup>2</sup> Beginning with its SIB Surcharge Request filing for Year Two, the Company may request a change from the estimated Cost/Unit (in the Commission approved Initial SIB Table I) due to inflation using the latest calendar year Consumer Price Index. This may be done only if the Initial SIB Plant Table I unit cost did not account for inflation.

| Replace 13 residential services (3/4" or 1") on Spotted Horse between Mustang and Westridge. The services are branched black poly lines (one service for two customers) that are failing at a high rate. These services are a priority because they were installed about 35 years ago, in 1979. Replacing the services will help reduce system water loss and improve customer pressure and flow with a single service for each customer. The service line replacements are for existing customers and not related to new growth. See Map No. S-3 in Exhibit CC-1 for the locations of the replacements. | Replace 37 residential services (3/4" or 1") on Buffalo between Mustang and Fountain Hills Blvd. The services are branched black poly lines (one service for two customers) that are failing at a high rate. These services are a priority because they were installed about 38 years ago, in 1976. Replacing the services will help reduce system water loss and improve customer pressure and flow with a single service for each customer. The service line replacements are for existing customers and not related to new growth. See Map No. S.4 in Exhibit CC-1 for the locations of the replacements. | Replace 9 residential services (3/4" or 1") on Garland between Buffalo and Palatial. The services are branched black poly lines (one service for two customers) that are failing at a high rate. The services are located on a short dead-end street off of Buffalo, which is scheduled for service line replacements in the same year (project S-4). Replacing the services will help reduce system water loss and improve customer pressure and flow with a single service for each customer. The service line replacements are for existing customers and not related to new growth. See Map No. S-5 in Exhibit CC-1 for the locations of the replacements. | Replace 43 residential services (3/4" or 1") on Pinto between Palomino and Fountain Hills Blvd. The services are branched black poly lines (one service for two customers) that are failing at a high rate. These services are a priority because they were installed about 38 years ago, in 1976. Replacing the services will help reduce system water loss and improve customer pressure and flow with a single service for each customer. The service line replacements are for existing customers and not related to new growth. See Map No. S-6 in Exhibit CC-1 for the locations of the replacements. |
|--|--|--|---|
| 7/13<br>completed,<br>see S-03<br>project map  | 28/37<br>completed,<br>see S-04<br>project map   | 3/9<br>completed,<br>see S-05<br>project map   | 31/43<br>completed,<br>see S-06<br>project map  |
| 6/2015   | 6/2015   | 6/2015   | 6/2015  |
| Spotted Horse  | Buffalo  | Garland  | Pinto   |
| \$50,450   | \$143,590  | \$34,927   | \$166,874   |
| n/a  | n/a  | n/a  | n/a   |
| \$3,881  | \$3,881  | \$3,881  | \$3,881   |
| Copper   | Copper   | Copper   | Copper  |
| %" & 1"  | %"& I"   | 3/1° & 1"  | % & 1"  |
| 13   | 37   | Φ  | 43  |
| 333  | 333  | 333  | 333   |
| S-3  | S-4  | S5   | S-6   |

|   |          |           | \$1,284,545 | Total Cost | Estimated |        |          |   |     |      |
|---|----------|-----------|-------------|------------|-----------|--------|----------|---|-----|------|
| Keplace 84 residential services (3/4 or 1 ) on El Pueblo between Fountain Hills Blvd and Caliente. The services are branched black poly lines (one service for two customers) that are failing at a high rate. These services are a priority because they were installed in 1972 and will be 43 years old in 2015. Additionally, the Town of Fountain Hills will be paving El Pueblo Road in 2015 and has requested that these services be replaced before the paving begins. Replacing the services will help reduce system water loss and improve customer pressure and flow with a single service for each customer. The service line replacements are for existing customers and not related to new growth. See Map No. S-22 in Exhibit CC-1 for the locations of the replacements. | 6/2015 c | El Pueblo | \$325,987   | r/a        | \$3,881   | Соррег | %. & I., | *************************************** | 333 | S-22 |

Revised 4/1/2014



### 2014

Project No: S-01 • PWSID: 07-017

# Chaparral District Fountain Hills

### project area: Ocotillo

project desciption:
Replace 4D residential services (3/4" or 1")
on Ocosilio
between Mustang and Fountain Hills Blvd.

- Service Previously Replaced
  - --- Water Main
- Completed Services 2014






WATER

Created: 1/1 3/2015

EPCOR Water 2013 - prepared by Engineering Mapping Southon - Phoenix, A.



# 2014 Project No: S-02 • PWSID: 07-017

## Chaparral District Fountain Hills

## project area: **Mustang**

project desciption: Replace 105 residential services (34" or 1") on Mustang between Palisades and Fountain Hils Blvd.

### Legend

- Service Previously Replaced
  - Service to be Replaced - Water Main
- Completed Services 2014



2355 W. Pinnade Peak Rd. Suite 300 Phoenix, AZ 85027



# Chaparral District Fountain Hills


project desciption:
Replace 13 residential services (3/4" or 17)
on Sported Horse
between Mustang and Westridge.

- Service Previously Replaced
  - Service to be Replaced Water Main
- Completed Services 2014



WATER

2014
Project No: S-04 • PWSID: 07-017 Chaparral District Fountain Hills WATER Service Previously Replaced project desciption:
Replace 37 residential services (3/4" or 1")
on Buffalo
between Mustang and Fountain Hills BNd. Completed Services 2014 project area: **Buffalo** Service to be Replaced Water Main Legend NA TARARUM 10810 10840 11000 W. Que de la Constantina del Constantina de la C 11260 AO SWATZUM OATO ONIMO BEAD OCOTILLO DR



# Chaparral District Fountain Hills

### project area: **Garland**

project desciption:
Replace 9 residential services (3/4\* or 1\*)
on Galland
between Buffalo and Palatial.

### Legend

- Service Previously Replaced
  - --- Water Main
- Completed Services 2014

2355 W. Pinnade Peak Rd. Suite 300 Phoenix, AZ 85027

WATER

created 1/13/2015 - Constitution of the Const

2014 Project No: S-06 • PWSID: 07-017 Chaparral District Fountain Hills Completed Services 2014 Service to be Replaced project area: project desciption: --- Water Main Legend MUSKRAT CA 10820 FOUNTAIN HILLS BLVD 10005 11012 11013 dis Ons like \$10 ON HAME MOIAN POWY WY 11227 11244 CATE ONIMO TO BURRO DR PINTO DR OCOTILLO DR

Replace 43 residential services (3/4" or 1") on Pinto between Palomino and Fountain Hills BMd.

- Service Previously Replaced

WATER

Crealed; Iff 3/2015 EVOR Water 2013 - prepared by Engineering Mapping Soutteen - Phoenix, AZ

## Chaparral City Water Company, PWSID No. 07-017 SIB PLANT TABLE I, 2-1 2014 Valve Replacements

Information to be included with SIB-Eligible Project Filings

| Provide narrative why Replacement Plant is necessary     replacement of existing plant that has exceeded its designated useful life and has worn out or is in deteriorating condition due to no fault of the utility     replacement of existing plant to address excessive water | loss [10% or more) - replacement of existing plant for other reasons supported by persuasive showing by utility | 2. Provide narrative explaining why this segment of plant is a priority. | 3. Provide narrative explaining how replacing this plant will benefit existing customers. | 4. Provide affirmation that Replacement Plant does not include the costs for extending or expanding facilities to serve new customers. | 5. Provide reference to related page No. in the submitted detailed Engineering Analysis supporting the need for SIB Engineering Analysis shall also include narrative explaining the utility's systematic assessment, inspection, maintenance and repair/replacement program. | Replace 23-6", 1-8", 4-12" valves (28 total) on Palomino between Palisades and Fountain Hills Blvd. Distribution system valves that are no longer functioning because they are primarily uncoated butterfly valves which are prone to uberculation. These valves are a priority because they were installed in 1976 and will be 38 years old in 2014. Replacing the valves decreases time required to shutdown water main in the event of main break or other system maintenance which reduces customer service disruption and decreases water loss during a main breaks. The valve replacements are not related to new growth. Map V-1 in Exhibit CC-1 shows the location of these valves. |
|---|---|--|---|--|---|---|
|   | Project<br>Status   |  |   |  |   | 1/28<br>completed,<br>see V-01<br>project map   |
|   | Expected<br>In-Service<br>Date  |  |   |  |   | 6/2015  |
|   | Site<br>(location<br>description)   |  |   |  |   | Palomino  |
| w plant)  | Subtotal<br>Cost<br>(estimated)   |  |   |  |   | \$136,862   |
| Replacement Plant Description (new plant)<br>(SIB-eligible plant)   | Cost/Unit (estimated) <sup>2</sup>  |  |   |  |   | n/a   |
| nt Plant De<br>(SIB-eligib  | Cost/Unit (estimated) <sup>1</sup>  |  |   |  |   | 6"-\$4,651<br>8"-\$5,201<br>12"-\$6,173   |
| placeme   | Material  |  |   |  |   | cast iron<br>with<br>rubberiz<br>ed<br>epoxy<br>coating   |
| Re  | Diameter/<br>Size   |  |   |  |   | 23-6"<br>1-8"<br>4-12"  |
|   | Units<br>(Quantity)   |  |   |  |   | 28  |
|   | NARUC<br>Acct No./<br>Plant   | 331 T&D<br>Mains/  | Valves  |  |   | 331   |
|   | Project<br>No.  |  | ,,,,  |  |   | V-1   |


 $<sup>^{\</sup>mathrm{1}}$  Per the Commission approved Initial SIB Table I.

<sup>&</sup>lt;sup>2</sup> Beginning with its SIB Surcharge Request filing for Year Two, the Company may request a change from the estimated Cost/Unit (in the Commission approved Initial SIB Table I) due to inflation using the latest calendar year Consumer Price Index. This may be done only if the Initial SIB Plant Table I unit cost did not account for inflation.

| Replace 31-6", 1-4", and 2-12" valves (34 total) on Mustang between Palisades and Fountain Hills Blvd. Distribution system valves are no longer functioning because they are primarily uncoated butterfly valves which are prone to ubbeculation. These valves are a priority because they were installed in 1977 and will be 37 years old in 2014. Replacing the valves decreases time required to shutdown water main in the event of main break or other system maintenance which reduces customer service disruption and decreases water loss during a main breaks. The valve replacements are not related to new growth. Map V-2 in Exhibit CC-1 shows the location of these valves. | Replace 1-6" valve on Spotted Horse between Mustang and Westridge. Distribution system valves are no longer functioning because they are primarily uncoated butterfly valves which are prone to tuberculation. This valve is a priority because it was installed in 1979 and will be 35 years and is needed in order to operate the only hydrants on this street. Replacing valves decreases time required to shutdown water main in the event of main break or other system maintenance which reduces customer service disruption and decreases water loss during a main breaks. The valve replacements are not related to new growth. Map V-3 in Exhibit CC-1 shows the location of this valve. | Replace 10-6" valves on Buffalo between Mustang and Fountain Hills Blvd. Distribution system valves are no longer functioning because they are primarily uncoated butterfly valves which are prone to tuberculation. These valves are a priority because they were installed in 1976 and will be 38 years old in 2014. Replacing the valves decreases time required to shutdown water main in the event of main break or other system maintenance which reduces customer service disruption and decreases water loss during a main breaks. The valve replacements are not related to new growth. Map V-4 in Exhibit CC-1 shows the location of these valves. | Replace 1-6" valve on Garland between Buffalo and Palatial. Distribution system valves are no longer functioning because they are primarily uncoated butterfly valves which are prone to tuberculation. This valve is suffering from corrosion and is the only way to isolate Garland Circle. Replacing valves decreases time required to shutdown water main in the event of main break or other system maintenance which reduces customer service disruption and decreases water loss during a main breaks. The valve replacements are not related to new growth. Map V-5 in Exhibit CC-1 shows the location of this valve. |
|---|---|--|---|
| 0/34<br>completed   | 0/1<br>completed  | 9/10<br>completed,<br>see V-04<br>project map  | 1/1<br>completed,<br>see V-05<br>project map  |
| 6/2015  | 6/2015  | 6/2015   | 6/2015  |
| Mustang   | Spotted Horse   | Buffalo  | Garland   |
| \$160,952   | \$4,651   | \$46,508   | \$4,651   |
| n/a   | п/а   | п/а  | п/а   |
| 4".\$4,431<br>6".\$4,651<br>12"-\$6,173   | \$4,651   | \$4,651  | \$4,651   |
| cast iron with rubberiz ed epoxy coating  | cast iron with rubberiz ed epoxy coating  | cast iron with rubberiz ed epoxy coating   | cast iron<br>with<br>rubberiz<br>ed<br>epoxy<br>coating   |
| 31-6"<br>1-4"<br>2-12"  | 6"  | .9   | 9   |
| 34  | -   | 10   |   |
| 331   | 331   | 331  | 331   |
| V-2   | V-3   | ٧-4  | ٧-5   |

| Revised 4/1/2014   |   |        |           | \$621,677 | Estimated Total Cost | Estimated   |   |   |                                | _                                 |  |
|--|---|--------|-----------|-----------|----------------------|---|---|---|--------------------------------|-----------------------------------|--|
| Replace 1-4 , 19-6 , 3-8 , 2-12 (33 total) valves on the Pueblo between Fountain Hills Blvd and Escalarte. Distribution system valves are no longer functioning because they are primarily uncoated butterfly valves which are prone to tuberculation. These valves were installed in 1973 and will be 42 years old in 2015. Replacing the valves decreases time required to shutdown water main in the event of main break or other system maintenance which reduces customer service disruption and decreases water loss during a main breaks. Additionally, the Town of Fountain Hills will be paving El Pueblo Road in 2015 and has requested that these valves be replaced before the paving begins. The valve replacements are not related to paving south. Map V-31 in Exhibit CC-1 shows the location of these valves. | 0/33<br>completed                             | 6/2015 | El Pueblo | \$168,186 | n/a                  | 4"-\$4,431<br>6"-\$4,651<br>8"-\$5,201<br>12"-\$6,173 | cast iron<br>with<br>rubberiz<br>ed<br>epoxy<br>coating | 1 | 1-4"<br>19-6"<br>5-8"<br>8-12" | 1-4"<br>19-6"<br>33 5-8"<br>8-12" |  |
| Replace 7-6" and 4-8" valves (11 total) on Ocotillo between Mustang and Fountain Hills Blvd. Distribution system valves are no longer functioning because they are primarily uncoated butterfly valves which are prone to tuberculation. These valves are a priority because they were installed in 1974 and will be 40 years old in 2014. Replacing the valves decreases time required to shutdown water main in the event of main break or other system maintenance which reduces customer service disruption and decreases water loss during a main breaks. The valve replacements are not related to new growth. Map V-7 in Exhibit CC-1 shows the location of these valves.   | 0/11<br>completed                             | 6/2015 | Ocotillo  | \$53,359  | n/a                  | 6"- <b>\$</b> 4,651<br>8"- <b>\$</b> 5,201            | cast iron with rubberiz ed epoxy coating                |   | 7-6"                           | 11 7-6"                           |  |
| Replace 10-6" valves on Pinto between Palomino and Fountain Hills Blvd. Distribution system valves are no longer functioning because they are primarily uncoated butterfly valves which are prine to tuberculation. These valves are a priority because they were installed in 1976 and will be 38 years old in 2014. Replacing the valves decreases time required to shutdown water main in the event of main break or other system maintenance which reduces customer service disruption and decreases water loss during a main breaks. The valve replacements are not related to new growth. Map V-6 in Exhibit CC-1 shows the location of these valves.  | 6/10<br>completed,<br>see V-06<br>project map | 6/2015 | Pinto     | \$46,508  | n/a                  | \$4,651   | cast iron with rubberiz ed epoxy coating                |   | ٠,                             | 01                                |  |

Revised 4/1/2014




Chaparral District Fountain Hills

project desciption: Replace 23-5", 1-8", 4-12" valves (28 total) on Palomino between Palisades and Fountain Hills Blvd.

- Valves previously replaced
- Street valve emergency replacement 2014



WATER



# Chaparral District Fountain Hills

### project area: **Buffalo**

- 😝 Valves previously replaced
- Street valve emergency replacement 2014



WATER

2014 Project No: V-05 • PWSID: 07-017 Street valve emergency replacems
Valves to be replaced 2014
Valves to be replaced
Water Main project area: Garland project desciption:
Replace 1-6' valve
on Garland
between Buffalo and Palatial. 2355 W. Pinnacle Peak Rd. Suite 300 Phoenix, AZ 85027 Legend dio Christis


# Chaparral District Fountain Hills

- 🕬 Valves previously replaced



WATER

Created: 1/16/2015



# Chaparral District Fountain Hills

project area: **Pinto** 

- 😝 Valves previously replaced



FEGER WATER

Created: 1/16/2015
EPCOR Water 2013 - propured by Engineering Mapping Solution - Proenty, A2

## Chaparral City Water Company, PWSID No. 07-017 SIB PLANT TABLE I, 3-1 2014 Hydrant Replacements

Information to be included with SIB-Eligible Project Filings

| Provide narrative why Replacement Plant is necessary     replacement of existing plant that has exceeded its designated useful life and has worn out or is in deteriorating condition due to no fault of the utility replacement of existing plant to address excessive water | loss (10% or more)  - replacement of existing plant for other reasons supported by persuasive showing by utility | Provide narrative explaining why this segment of plant is a priority.     Provide narrative explaining how replacing this plant will benefit existing customers. | 4. Provide affirmation that Replacement Plant does not include the costs for extending or expanding facilities to serve new customers. | 5. Provide reference to related page No. in the submitted detailed Engineering Analysis supporting the need for SIB Engineering Analysis shall also include narrative explaining the utility's systematic assessment, inspection, maintenance and repair/replacement program. | Replace 8 fire hydrants on Palomino between Palisades and Fourtain Hills Blvd. The fire hydrants are in deteriorating condition and are approximately 35 years old. These are Dresser hydrants, for which we can no longer obtain repair parts. Three hydrants on this street have already needed replacement within the last 6 years. Replacing the hydrants will improve fire flow availability and response times in the event of fire at a customer's home or business. The hydrant replacements are for existing customers and not related to new growth. See the map for Project H-1 in Exhibit CC-1 which shows the locations of the future replacements. |
|---|--|--|--|---|--|
|   | Project<br>Status  |  |  |   | 0/8<br>completed   |
|   | Expected<br>In-Service<br>Date   |  |  |   | 6/2015   |
|   | Site<br>(location<br>description)  |  |  |   | Palomino   |
| w plant)  | Subtotal<br>Cost<br>(estimated)  |  |  |   | \$18,093   |
| Replacement Plant Description (new plant)<br>(SIB-eligible plant)   | Cost/Unit<br>(estimated) <sup>2</sup>  |  |  |   | ה/מ  |
| nt Plant Descriptior<br>(SIB-eligible plant)  | Cost/Unit<br>(estimated) <sup>1</sup>  |  |  |   | \$2,262  |
| placeme   | Material   |  |  |   | Cast<br>Iron/<br>Avk<br>Wet<br>Barrel  |
| Re  | Diameter/<br>Size  |  |  |   | n/a  |
|   | Units<br>(Quantity)  |  |  |   | ∞  |
|   | NARUC<br>Acct No./<br>Plant  | 335<br>Hydrants  |  |   | 335  |
|   | Project<br>No.   |  |  |   | Ŧ  |

<sup>1</sup> Per the Commission approved Initial SIB Table I.

<sup>&</sup>lt;sup>2</sup> Beginning with its SIB Surcharge Request filing for Year Two, the Company may request a change from the estimated Cost/Unit (in the Commission approved Initial SIB Table I) due to inflation using the latest calendar year Consumer Price Index. This may be done only if the Initial SIB Plant Table I unit cost did not account for inflation.

| Replace 10 fire hydrants on Mustang between Palisades and Fountain Hills Blvd. The fire hydrants are in deteriorating condition and are 37 years old. These are Dresser hydrants, for which we can no longer obtain repair parts. One hydrant on this street has already needed replacement within the last 6 years. Replacing the hydrants will improve fire flow availability and response times in the event of fire at a customer's home or business. The hydrant replacements are for existing customers and not related to new growth. See the map for Project H-2 in Exhibit CC-1 which shows the locations of the future replacements. | Replace I fire hydrant on Spotted Horse between Mustang and Westridge. The fire hydrant is in deteriorating condition and is 34 years old. This is a Dresser hydrant, for which we can no longer obtain repair parts. Replacing the hydrant will improve fire flow availability and response times in the event of fire at a customer's home or business. The hydrant replacement is for existing customers and not related to new growth. See the map for Project H-3 in Exhibit CC-1 which shows the location of the future replacement. | Replace I fire hydrant on Buffalo between Mustang and Puma. The fire hydrant is in deteriorating condition and is 37 years old. This is a Dresser hydrant, for which we can no longer obtain repair parts. The other 3 hydrants on this street have already needed replacement. Replacing the hydrant will improve fire flow availability and response times in the event of fire at a customer's home or business. The hydrant replacement is for existing customers and not related to new growth. See the map for Project H-4 in Exhbit CC-1 which shows the location of the future replacement. | Replace 10 fire hydrants on Sunburst between Palisades and Sycamore. The fire hydrants are in deteriorating condition and 2 hydrants on this street have already needed replacement. These are Dresser hydrants, for which we can no longer obtain repair parts. Two hydrants on this street have already needed replacement within the last 6 years. Replacing the hydrants will improve fire flow availability and response times in the event of fire at a customer's home or business. The hydrant replacements are for existing customers and not related to new growth. See the map for Project H-5 in Exhibit CC-1 which shows the locations of the future replacements. |
|--|--|---|---|
| 0/10<br>completed  | 0/1<br>completed   | 0/1<br>completed  | 0/10<br>completed   |
| 6/2015   | 6/2015   | 6/2015  | 6/2015  |
| Mustang  | Spotted Horse  | Buffalo   | Sunburst  |
| \$22,616   | \$2,262  | \$2,262   | \$22,620  |
| 17/3   | n/a  | n/a   | n/a   |
| \$2,262  | \$2,262  | \$2,262   | \$2,262   |
| Cast<br>Iron/<br>AVK<br>Wet<br>Barrel  | Cast<br>Iron/<br>AVK<br>Wet<br>Barrel  | Cast<br>Iron/<br>AVK<br>Wet<br>Barrel   | Cast<br>Iron/<br>AVK<br>Wet<br>Barrel   |
| n/a  | 17/8   | n/a   | n/a   |
| 01   |  | -   | 01  |
| 335  | 335  | 335   | 335   |
| H-2  | H-3  | H-4   | H-5   |

|   |  |        |                      | \$453,491 | Total Cost   \$453,491 | Estimated |                                       |     |   |  |
|---|--|--------|----------------------|-----------|------------------------|-----------|---------------------------------------|-----|---|--|
| Replace 7 fire hydrants on Ocotillo between Mustang and Fountain Hills Blvd. The fire hydrants are in deteriorating condition and are approximately 39 years old. These are Dresser hydrants, for which we can no longer obtain repair parts. Replacing the hydrants will improve fire flow availability and response times in the event of fire are customers's home or business. The hydrant replacements are for existing customers and not related to new growth. See the map for Project H-7 in Exhibit CC-1 which shows the locations of the future replacements.   | C C C C C C C C C C C C C C C C C C C  | 6/2015 | Ocotillo             | \$15,831  | n/a                    | \$2,262   | Cast<br>Iron/<br>AVK<br>Wet<br>Barrel | n/a | 7 |  |
| Replace 4 fire hydrants on Burro and Pincushion between Palomino and Ocotillo. The fire hydrants are in deteriorating condition and are approximately 37 years old. These are Dresser hydrants, for which we can no longer obtain repair parts. Replacing the hydrants will improve fire flow availability and response times in the event of fire at a customer's home or business. The hydrant replacements are for existing customers and in critetie to new growth. See the map for Project H-6 in Exhibit CC-I which shows the locations of the future replacements. | 0/4 o o completed find a n n n n n n v | 6/2015 | Pinto,<br>Pincushion | . \$9,046 | n/a                    | \$2,262   | Cast<br>Iron/<br>AVK<br>Wet<br>Barrel | п/а | 4 |  |

Revised 4/1/2014

## Chaparral City Water Company, PWSID No. 07-017 SIB PLANT TABLE I, 4-1 2014 Meter Replacements

Information to be included with SIB-Eligible Project Filings

Revised 4/1/2014

<sup>&</sup>lt;sup>1</sup> Per the Commission approved Initial SIB Table I.

<sup>&</sup>lt;sup>2</sup> Beginning with its SIB Surcharge Request filing for Year Two, the Company may request a change from the estimated Cost/Unit (in the Commission approved Initial SIB Table I) due to inflation using the latest calendar year Consumer Price Index. This may be done only if the Initial SIB Plant Table I unit cost did not account for inflation.